




FIG. 2

ENLARGED IN FIG. 5B



ENLARGED IN FIG. 5C

FIG. 3





FIG.4



ENLARGED DIAGRAM IN VERTICAL SCANNING DIRECTION





FIG. 5B

HORIZONTAL SCANNING  
DIRECTION

FIG. 5C



ENLARGED DIAGRAM IN HORIZONTAL SCANNING DIRECTION

FIG.6A

HORIZONTAL SCANNING DIRECTION

FIG.6B

HORIZONTAL SCANNING  
DIRECTION

FIG.6C

VERTICAL SCANNING  
DIRECTION

HORIZONTAL  
SYNCHRONIZATION  
SENSOR

23

FIG.7A

FIG.7B

FIG.7C




FIG.8A




FIG.8B




FIG.8C




FIG.9A




FIG.9B




FIG.10





FIG.11









FIG.14




FIG.15




FIG.16




FIG.17





FIG.18

ENLARGED DIAGRAM IN VERTICAL SCANNING DIRECTION



ENLARGED DIAGRAM IN HORIZONTAL SCANNING DIRECTION